

Safety Alert

Mobile Elevating Work Platforms (MEWP)

Basket attachment to Main Boom

Bolts on the main knuckle of the MEWP that joins the basket to the Main Boom were found to be loose and not aligned as per the painted torque marks. One of the eight bolts was finger tight only and able to be removed by hand.



Actions taken post inspection:

- All MEWPs on the project (6 in total) were tagged-out.
- Hire company called to site to discuss findings.
- Full inspection of all MEWPS by qualified mechanic.
- Confirmation of OEMs required torque for the bolts requested.
- Review of events that took place Pre delivery to site.



Action for all projects where applicable

- Check bolt torque on all MEWPs currently onsite.
- MEWP plant onboarding & maintenance checks to include inspections of bolts.

