


## REJECTION CRITERIA FOR ROUND SLING

Round slings must be inspected before each use to detect possible damages or errors



Welding spark damage




Heat and friction damage



Knot




Visible core




Horizontal and/or vertical cuts



Faulty connection



Label can not be read



Chemical damage